



OPERATIONAL OBSERVATIONS

Below are images representing areas of attention on District owned facilities. These reflect the decayed nature of the existing aged facilities and areas warranting either replacement or retrofitting. These photos are typical, but not exhaustive as many more demonstrable problem areas are prevalent.

WASTE WATER TREATMENT PLANT (WWTP):







SANITARY SEWER LINE REPAIRS:

